



# Department of Energy

ALBUQUERQUE OPERATIONS  
ROCKY FLATS AREA OFFICE  
P O BOX 928  
GOLDEN COLORADO 80402-0928

December 31, 1987

Mr. David Shelton, Director  
Hazardous Materials and  
Waste Management Division  
Colorado Department of Health  
4210 East 11th Avenue  
Denver, CO 80220

Mr. Robert L. Duprey, Director  
Waste Management Division  
U.S. Environmental Protection Agency  
Region VIII  
One Denver Place  
999 18th Street, Suite 1300  
Denver, CO 80202-2413

Gentlemen

Enclosed are two copies of the Draft Remedial Investigation Report for the 903 Pad, East Trenches, and Mound Areas. This report is submitted in accordance with the schedule established in my letter to you of February 16, 1987, which stated that the remedial investigations for these areas would be accelerated as they were identified in our 1986 installation-wide hydrogeological characterization as likely contributors to on-site ground water contamination. As you recall, the remedial investigation report for our high priority sites on the 881 Hillside was submitted on July 1, 1987 in accordance with the Compliance Agreement, and we are currently revising the report to accommodate your suggestions.

This enclosed report is submitted in draft form for your review and comment. We look forward to discussing the results of this report and incorporating your comments as well as any additional data you may request into a final report.

We would like to propose a special briefing for the public on the results of the enclosed report to follow the monitoring data exchange at the State Information Exchange Meeting scheduled for January 26, 1988.

If you have any concerns about our proposed briefing, questions about the information enclosed, or if you would like to meet with us to discuss the results prior to the public briefing, please contact Mr. John Krueger of my staff at 966-4871.

Sincerely,

*Albert E. Whiteman*  
Albert E. Whiteman

*for* Area Manager

Enclosure (2)

ADMIN RECORD

A 000005968